


## **MAIN MARK**

NOTE: CARTON MATERIAL MUST BE A=A

P/O: XXXXXX P/N: 181229 Q'TY: 24 C/NO:: Cxxx

MADE IN CHINA



## **SIDE MARK**

P/N: 181229
QTY: 24 PCS
N.W.: 12.98 KGS
G.W.: 14.11 KGS
Date Code: XX-XXXX
Vender Code: PS00999

Carton Size: 20.67"(L)\*13.58"(W)\*8.86"(H)

Carton Quantity: 24 pcs
Carton Weight: 31.11 LBS

## Packing Instruction:

- First of all, protect the connector with dust covers, coil the cable (see attached). Secure the cable with cable tie, and then pack each cable with an individual PE bag. Customer's label must be put on the center of the PE bag.
- 2. Seal the PE bag with heat sealing machine.
- Use a waterproof bag to pack the products before going into master carton. Make sure each individual cable is staggered and positioned tidily. A paperboard is needed in both the bottom and the top of the products.
- 4. See shipping mark on the left.

