





| REVISION INFORMATION | | | |
|----------------------|-----------|-------------|--------------------|
| Rev. | Rev. Date | Modified By | Brief Description |
| 1.0 | 2022-3-15 | Нуро | Release to product |


FRONT














MAIN MARK

P/O: XXXXXX P/N: 184044
Q'TY: 160
C/NO.: Cxxx





SIDE MARK



Carton Size: 20.67"(L)*13.58"(W)*8.86"(H)

Carton Quantity: 160 pcs
Carton Weight: 32.40 LBS

Packing Instruction:

1.First of all, protect the connector with dust covers, coil the cable (see attached). Secure the cable with cable tie, and then pack each cable with an individual PE bag,10pcs cable in a clear big bag, The label is attached to the PE bag.

- 2. Seal the PE bag with heat sealing machine.
- 3. Use a waterproof bag to pack the products before going into master carton. Make sure each individual cable is staggered and positioned tidily. A paperboard is needed in both the bottom and the top of the products.
- 4. See shipping mark on the left.

