



NOTE: CARTON MATERIAL MUST BE A=A




BACK









MAIN MARK

Label
Size:50*20mm

50


1ft USB Type C to
Type C Cable

Size:110*70mm

Label

Label: Size:10 x 5 mm

SIDE MARK



Carton Size: 20.67"(L)*13.58"(W)*8.86"(H)

Carton Quantity: xxx pcs Carton Weight: xxxx LBS

Packing Instruction:

1.Coil the cable (see attached). Secure the cable with cable tie, and then pack each cable with an PE bag, The label is attached to the OPP bag.

- 2. Seal the PE bag,
- 3. Use a waterproof bag to pack the products before going into master carton. Make sure each individual cable is staggered and positioned tidily. A paperboard is needed in both the bottom and the top of the products.
- 4. See shipping mark on the left.

